

Lattice Radiant Software 3.1 Release Notes

Welcome to Lattice Radiant® software, the complete design environment for Lattice Semiconductor Field Programmable Gate Arrays (FPGAs).

What's New in Radiant Software 3.1

▶ Device Support:

- Certus™-NX Auto Device PSR (LFD2NX)

▶ Tool and Other Enhancements:

- **Device Constraint Editor** – The default configuration of JTAG_PORT, DONE_PORT, INITN_PORT, and PROGRAMN_PORT has been set to “ENABLE.”
- **IO Eye-Opening Monitor (IO EOM)** – The IO EOM feature has been added to the Reveal Analyzer/Controller tool for devices with PCS hard IP such as LFCPNX device family.
- **IP Encryption Flow** – Improved protection for IEEE1735 compliant IP Encryption Flow.
- **IP Packager** – The IP Packager tool has been updated. Radiant software now uses the Propel software version of IP Packager.
- **JTAG Debug** – This new feature has been added to support simultaneous debugging of processor system and Reveal hardware debugging.
- **Standalone Timing Analyzer** – This new feature can be used to run experimental timing analysis on designs using post-synthesis, post-map, post-PAR Unified Design Database (.udb), and associated timing constraints specified in the .pdc file of the design. The Standalone Timing Analyzer content has been added to the Radiant Software Help.
- **VHC File Extension Support** – This release of the Radiant software adds the ability to recognize files with the .vhc file extension as VHDL files. VHC files inherit the same characteristics as .vhd (VHDL) files.
- **Virtual IO Ports Support** – This new feature allows easy timing/resource estimation for over exceeding IO designs. A “Virtual” column has also been added to the Device Constraint Editor.

Support for Third-Party Synthesis and Simulator Tools

The Synopsys Synplify Pro® for Lattice synthesis tool and the Siemens ModelSim® Lattice Edition simulator tool are included in the Radiant software.

- ▶ **Synopsys Synplify Pro FPGA synthesis software version R-2021.03LR-SP1**
 - ▶ Release Notes for Synplify Pro are located in `..\<install_directory>\radiant\3.1\synpbase\doc\`. The file name is `release_notes.pdf`.
 - ▶ A full set of documents for Synplify Pro are also located in `..\<install_directory>\radiant\3.1\synpbase\doc\`.
- ▶ **Siemens ModelSim Lattice Edition 2021.4 revision 2021.10**
 - ▶ Release Notes for ModelSim Lattice Edition are located in `..\<install_directory>\radiant\3.1\modeltech\`. The file names are `RELEASE_NOTES.html` or `RELEASE_NOTES.txt`.
 - ▶ A full set of documents for ModelSim Lattice Edition are located in `..\<install_directory>\radiant\3.1\modeltech\doc\`.
- ▶ **Siemens Questa® 2020.4**
- ▶ **Cadence Xcelium® 20.09-s004**
- ▶ **Synopsys VCS® Q-2020.03**

Updating Projects from an Earlier Version

If you want to work on a design project created with an earlier version of Radiant software, it may be necessary to re-generate some IP, per the procedures described in the following table. These procedures adapt the project for the changes in Radiant software.

Find out which version of Radiant software your project was created with. Then work through the changes for that and every later version, starting with the earliest and going to the most recent. For example, if your project was created with Radiant software 1.0, you would start with the changes for Radiant software 1.0. After completing those changes, you would work on the changes for Radiant software 2.0, and so on.

Once saved, the project will not be compatible with earlier Radiant software versions.

Versions	IP		IP Regeneration Procedures
	CrossLink-NX (LIFCL), Certus-NX (LFD2NX), and CertusPro-NX	ice40UP	
3.1	PLL (Phase Locked Loop)	N/A	These IP used in designs created in Radiant 3.0 must be re-generated in Radiant 3.1
	DDR_Generic (DDR Generic Interfaces)		
	GDDR7:1 (LVDS Interface)		
	DDR_MEM (DDR Memory Interfaces)		
	LPDDR4_MEM (LPDDR4 Memory Interface)		
	MIPI_DPHY (MIPI D-PHY Interface)		
	ADC_Sequencer (Analog to Digital Converter)		
	Large_RAM_DP (Dual Port Large RAM)		
	Large_RAM_DP_True (True Dual Port Large RAM)		
	Large_RAM_SP (Single Port Large RAM)		
	Large_ROM (Read-only Large Memory)		
	FIFO_DC (Dual Clock FIFO)		
	Complex Mult		
	MPCS (Multi-Protocol PCS)		
3.0	PLL (Phase Locked Loop)	N/A	These IP used in designs created in Radiant 2.2.1 must be re-generated in Radiant 3.0
	DDR_Generic (DDR Generic Interfaces)		
	GDDR7:1 (LVDS Interface)		
	DDR_MEM (DDR Memory Interfaces)		
	MIPI_DPHY (MIPI D-PHY Interface)		
	LFSR (Linear Feedback Shift Register)		
	ADC_Sequencer (Analog to Digital Converter)		
	RAM_DP_True (True Dual Port RAM)		
	RAM_DQ (Single Port RAM)		
	ROM (Read-only Memory)		
	FIFO		
	FIFO_DC		
	Shift Register		
	Sine-Cosine Table		
Convert			
2.2.1	PLL (Phase Locked Loop)	N/A	These IP used in designs created in Radiant 2.2 must be re-generated in Radiant 2.2.1
	DDR_Generic (DDR Generic Interfaces)		
	GDDR7:1 (LVDS Interface)		
	DDR_MEM (DDR Memory Interfaces)		
	MIPI_DPHY (MIPI D-PHY Interface)		
	LFSR (Linear Feedback Shift Register)		
	ADC_Sequencer (Analog to Digital Converter)		
	RAM_DP (Pseudo Dual Port RAM)		
2.2	PLL (Phase Locked Loop)	PLL (Phase Locked Loop)	These IP used in designs created in Radiant 2.1 must be re-generated in Radiant 2.2
	DDR_Generic (DDR Generic Interfaces)		
	GDDR7:1 (7:1 LVDS Interface)		
	SDR (Single Data Rate)		
	DDR_MEM (DDR Memory Interfaces)		
	ADC (Analog to Digital Converter)		
	SEDC (Soft Error Detection/Correction)		
	Sin_Cos_Table (Sine Cosine Table)		
	OSC (Oscillator)		
	RAM_DQ (Single Port RAM)		
	RAM_DP_True (True Dual Port RAM)		

Versions	IP		IP Regeneration Procedures
	CrossLink-NX (LIFCL), Certus-NX (LFD2NX), and CertusPro-NX	iCE40UP	
	FIFO		
	FIFO_DC (FIFO Dual Clock)		
2.1	PLL (Phase Locked Loop)	N/A	These IP used in designs created in Radiant 1.0, 2.0, or 2.0 SP1 must be re-generated in Radiant 2.1
	GDDR7:1 (7:1 LVDS Interface)		
	DDR_MEM (DDR Memory Interfaces)		
	DDR_Generic (DDR Generic Interfaces)		
	MIPI_DPHY (MIPI Interface)		
	ADC (Analog to Digital Converter)		
	SEDC (Soft Error Detection/Correction)		
	OSC (Oscillator)		
<p>All IP:</p> <ul style="list-style-type: none"> Starting with Radiant 2.1, PMIs for any IP created in Radiant software versions 1.0, 2.0, 2.0 SP1, user must add the Family attribute in all PMI instantiations. For designs created in previous versions of Radiant software (2.0 or prior), it is necessary to re-generate PLL IP in Radiant software 2.1. Otherwise, Radiant software 2.1 will issue an error when the previous generated PLL IP is detected in the design. Designs created using Radiant Software 2.0 SP1 with PLL will work without any errors. The IO_TYPE HDL attribute default value has been changed since Radiant 2.0 SP1 from LVCMOS18 to LVCMOS33. If a LARGE_RAM IP generated from a previous Radiant version needs to be re-configured in Radiant 2.1, the IP must be re-created. 			

The following server IP are not compatible with Radiant 3.0. Use the latest versions of the IP that work with Radiant 3.0:

- ▶ I2S Master version 1.0.3
- ▶ UART 16550 version 1.0.4
- ▶ DDR3 SDRAM Controller version 1.1.1
- ▶ DDR3 SDRAM Controller version 1.2.1
- ▶ LPDDR2 SDRAM Controller Lite version 1.1.1
- ▶ LPDDR2 SDRAM Controller Lite version 1.2.1

Migration Changes to Notice from Earlier Release

Hold Time Calculation Issue

Bug Number: DNG-11733

There was a hold time calculation error that was existent in Radiant 3.0 and fixed in the current Radiant 3.1 in which designs from Radiant 3.0 should make note of this issue.

For example, if your design has an output delay of +1.00 ns added to the constraints (set_output_delay), during hold calculations, this delay should be ideally subtracted from the destination clock path delay.

Instead in Radiant 3.0 during hold calculations, this delay was added to the destination clock path delay resulting in an erred calculation.

Workaround: In Radiant 3.0, for the aforementioned example, instead of +1.00 ns, you should change the delay to -1.00ns to correct the hold calculations.

sysConfig Paramters Settings Default value Change

Bug Number: DNG-12094

In Radiant 3.0 software, the default configuration for CrossLink related devices differs from previous products which caused some customer support confusion. Existing default settings for SDM ports signals (DONE, INITN, PROGRAMN) blow fuses and are irreversible. In Radiant 3.0, the default sysConfig settings for JTAG_PORT, DONE_PORT, INITN_PORT and PROGRAMN_PORT was DISABLE and in Radiant 3.1 the default setting is ENABLE.

Enacting such a change will preserve JTAG port and PROGRAMN port for device configuration activities by default, matching previous device behavior. The customer can optionally disable the ports if explicitly desired to increase GPIO or reduce static power. Furthermore, if a design failure is encountered due to not having enough PIO, the following constraint can be added to allow sysConfig shared pins to be used as GPIO.

Workaround: Please change the sysConfig setting to DISABLE in Device Constraint Editor (DCE) or add the following sysConfig constraint to .pdc constraint file:

```
ldc_set_sysconfig {JTAG_PORT=DISABLE DONE_PORT=DIABLE INITN_PORT=DISABLE  
PROGRAMN_PORT=DISABLE}
```

Help Resources

Available information resources for the Radiant software include the following:

- ▶ Online Help updated with CrossLink-NX (LIFCL), Certus-NX (LFD2NX), and CertusPro-NX (LFCPNX) content.
- ▶ To view the Online Help, start the Lattice Radiant software and select the  “Getting Started” icon under Information Center.

System Requirements

The following shows the basic system requirements for Radiant software:

- ▶ Intel Pentium or Pentium-compatible PC
- ▶ 64-bit OS:

Lattice Radiant Software 3.1 Release Notes
Release Notes – December 14, 2021

- ▶ Windows 10
- ▶ Red Hat Enterprise Linux 7.8 or 8.2
- ▶ Ubuntu version 18.04 LTS or 20.04 LTS
- ▶ Approximately 10 GB free disk space
- ▶ Computer Memory Requirement: 16 GB Recommended for running a single project. If running multiple projects, the memory requirement will be higher.
- ▶ 1024 X 768 graphics display
- ▶ Network adapter for license and network connectivity
- ▶ A Web browser with JavaScript capability
- ▶ Acrobat Reader

Known Issues for Radiant 3.1

The following are known issues for the Radiant Software 3.1.

MAP incorrectly reports number of DPHY and PCIE/ADC resources for CrossLink-NX (LIFCL) QFN72 package.

For assistance with this issue, please contact Lattice Technical Support.

Devices affected: CrossLink-NX (LIFCL)

Bug number: DNG-8297

When simulating Generic DDR, there may be a mismatch in the RTL and post-route simulation. Silicon is not affected.

For assistance with this issue, please contact Lattice Technical Support.

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX), CertusPro-NX (LFCPNX)

Bug number: DNG-9639

CSI-2/D-PHY Transmitter IP hangs during Post synthesis/PAR simulations.

For some configurations of CSI-2/DSI D-PHY-TX IP, post-synthesis and post-PAR simulation hangs (runs indefinitely without stopping) when LSE is used.

Workaround: Use Synplify Pro for synthesis and generating the post-PAR netlist if you run into this issue.

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX)

Bug number: DNG-9697

For some SystemVerilog designs, Synplify Pro fails to identify multi-driven nets and the flow passes with no errors.

Workaround: Check the design for multi-driven nets and run the flow using LSE to verify.

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX), CertusPro-NX (LFPCNX)

Bug number: DNG-10132

Modify default INIT value for HardDPHY RX soft IP when running at DPHY v1.1 data rate (<=1.5 Gbps).

When Hard DPHY is used, the input Tsu/Thd is unbalanced resulting in marginal Tsu performance at line rate <= 1.5 Gbps in this release. The following devices and IP are affected:

Device: Crosslink-NX (LIFCL)

IP: MIPI_DPHY (Hard DPHY, Receive Mode)

Workaround: To satisfy datasheet specification compliance, it is necessary to re-center the Tsu/Thd using the Manual De-Skew Calibration Delay Control feature in the Hard DPHY by performing the following on the generated RTL:

If MIPI_DPHY IP is used as the Receive interface with the Hard DPHY option at Data Rate <= 1.5 Gbps, modify the DPHY module instantiation's hard coded TEST_PATTERN[31:0] parameter setting from "0b00000000000000000000000000000000" (0x00000000) to "0b10000000001000000000000000000000" (0x80200000) in the <instance_name>_ipgen_lsc_mipi_wrapper_rx module inside <instance_name>.v which is located in the RTL files folder of the generated IP.

Devices affected: CrossLink-NX (LIFCL)

Bug number: DNG-10731

When you program a target device with designs involving EBRs with initial data, the initial data programmed into the EBRs may output incorrectly.

Workaround: Power cycle every time and then re-download.

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX), CertusPro-NX (LFPCNX)

Bug number: DNG-11514

When Reveal is used with mixed language design projects, synthesis may fail using both LSE and Synplify Pro.

For assistance with this issue, please contact Lattice Technical Support.

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX), CertusPro-NX (LFCPNX)

Bug number: DNG-11576

ADC Soft-IP “ADC Clock Divide” value must be a string.

The parameter .CLK_DIV must be passed to the ADC primitive as a string instead of an integer.

Workaround: Modify line 312 of the IP/lifcl/adc_core/lsc_adc_core.v RTL:

From: .CLK_DIV(CLK_DIV)

To: .CLK_DIV(SETUP_CLK_DIV)

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX), CertusPro-NX (LFCPNX)

Bug number: DNG-12220

When Reveal Controller is used for updating the PCS register (reg80) through the controller, it will cause the PCS Register value to be stuck at a value during successive writes.

Workaround: Re-download the bitstream.

Devices affected: CertusPro-NX (LFCPNX)

Bug number: DNG-12235

If you have a Hard IP in the design and are controlling it with Reveal Controller, Reveal Controller logic will overwrite the user logic which controls the Hard IP.

If LMMI bus IP is used as part of your design for dynamic update, it is recommended to not use the Reveal Controller for hard IP because the user design controlling the hard IP will be overwritten by Reveal Controller Logic.

Hard IPs: DPHY, I2CFIFO, PLL, PCS, PCIELL, SGMIIICDR

Devices affected: CrossLink-NX (LIFCL), Certus-NX (LFD2NX), CertusPro-NX (LFCPNX)

Bug number: DNG-12253

Reveal Eye Opening Diagram cannot be generated on Linux OS.

As the title reads, the eye diagram can only be generated currently in Windows OS and not on any Linux OS (Ubuntu, CentOS, RedHat).

Workaround: Use the Windows platform when generating the eye diagram.



Devices affected: CertusPro-NX (LFCPNX)

Bug number: DNG-12259