



Timer/Counter IP

IP Version: v1.5.0

Release Notes

FPGA-RN-02022-1.1

June 2026

Disclaimers

Lattice makes no warranty, representation, or guarantee regarding the accuracy of information contained in this document or the suitability of its products for any particular purpose. All information herein is provided AS IS, with all faults, and all associated risk is the responsibility entirely of the Buyer. The information provided herein is for informational purposes only and may contain technical inaccuracies or omissions, and may be otherwise rendered inaccurate for many reasons, and Lattice assumes no obligation to update or otherwise correct or revise this information. Products sold by Lattice have been subject to limited testing and it is the Buyer's responsibility to independently determine the suitability of any products and to test and verify the same. LATTICE PRODUCTS AND SERVICES ARE NOT DESIGNED, MANUFACTURED, OR TESTED FOR USE IN LIFE OR SAFETY CRITICAL SYSTEMS, HAZARDOUS ENVIRONMENTS, OR ANY OTHER ENVIRONMENTS REQUIRING FAIL-SAFE PERFORMANCE, INCLUDING ANY APPLICATION IN WHICH THE FAILURE OF THE PRODUCT OR SERVICE COULD LEAD TO DEATH, PERSONAL INJURY, SEVERE PROPERTY DAMAGE OR ENVIRONMENTAL HARM (COLLECTIVELY, "HIGH-RISK USES"). FURTHER, BUYER MUST TAKE PRUDENT STEPS TO PROTECT AGAINST PRODUCT AND SERVICE FAILURES, INCLUDING PROVIDING APPROPRIATE REDUNDANCIES, FAIL-SAFE FEATURES, AND/OR SHUT-DOWN MECHANISMS. LATTICE EXPRESSLY DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY OF FITNESS OF THE PRODUCTS OR SERVICES FOR HIGH-RISK USES. The information provided in this document is proprietary to Lattice Semiconductor, and Lattice reserves the right to make any changes to the information in this document or to any products at any time without notice.

Inclusive Language

This document was created consistent with Lattice Semiconductor's inclusive language policy. In some cases, the language in underlying tools and other items may not yet have been updated. Please refer to Lattice's inclusive language [FAQ 6878](#) for a cross reference of terms. Note in some cases such as register names and state names it has been necessary to continue to utilize older terminology for compatibility.

Contents

Contents 3

1. Introduction 4

 Timer/Counter IP v1.5.0 4

 Timer/Counter IP v1.4.0 4

 Timer/Counter IP Earlier Versions 4

References 5

Technical Support Assistance 6

1. Introduction

This document contains the Release Notes for the Timer/Counter IP. For specific details about the IP and driver, refer to the following:

- [Timer/Counter IP User Guide \(FPGA-IPUG-02139\)](#)
- [Timer/Counter Driver API Reference \(FPGA-TN-02425\)](#)

Timer/Counter IP v1.5.0

Software	Software Version	Summary of Changes
Lattice Radiant	2026.1	• Fixed an issue where the internal counter did not reset when a timeout was asserted while the prescaler was disabled. • Added device-specific clock frequency constraints for MachXO4 devices. • Updated testbench files to fix a simulation hang issue that occurred when <i>SWTRIG_EN_TEST_0</i> was the selected test in configurations where the number of timers is fewer than 4. • Driver update v26.01.00: • Simplified the <i>gp_timer_config</i> function. • Removed the dependency on <i>reg_access.h</i>. • Added macros for register access. • Removed the unused prescaler ratio macro. • Added <i>gp_timer_enable_interrupt</i> and <i>gp_timer_disable_interrupt</i>. • Enabled calling <i>gp_timer_start</i> without passing a callback function.

Timer/Counter IP v1.4.0

Software	Software Version	Summary of Changes
Lattice Radiant	2024.2	Fixed the bug where the timeout is asserted when Software-Controlled Retrigger is disabled.

Timer/Counter IP Earlier Versions

IP Version	Summary of Changes
1.3.1	Fixed an issue where the interrupt did not assert in some configurations and addressed the missing AHBL memory map.
1.3.0	• Fixed an issue where the PREADY response was not generated for all addresses, causing the internal counter to become stuck. • Updated the driver.
1.2.2	Fixed GUI settings issues.
1.2.1	Fixed the Python script issue when the number of timers equals 1.
1.2.0	• Added AHB-Lite support. • Updated the prescaler ratio to 1:2 to avoid IP generation issues.
1.1.1	Added the driver folder.
1.1.0	• Fixed the SNAPSHOT register readback. • Fixed an issue with updating the internal counter reload value through the PERIOD register.
1.0.0	Initial release.

References

- [Timer/Counter IP User Guide \(FPGA-IPUG-02139\)](#)
- [Timer/Counter Driver API Reference \(FPGA-TN-02425\)](#)
- [Avant-E](#) web page
- [Certus-N2](#) web page
- [Certus-NX](#) web page
- [CrossLink](#) web page
- [Timer/Counter IP Core](#) web page
- [Lattice Propel Design Environment](#) web page
- [Lattice Radiant Software](#) web page
- [Lattice Insights](#) web page for Lattice Semiconductor training courses and learning plans

Technical Support Assistance

Submit a technical support case through www.latticesemi.com/techsupport.

For frequently asked questions, refer to the Lattice Answer Database at www.latticesemi.com/Support/AnswerDatabase.



www.latticesemi.com